

Opacity Methods Compliance Assistance

Conference Call
September 1, 2015
9:30 a.m. – 10:30 a.m.

Several different visual test methods exist for measuring opacity. Any facility that is required to conduct one of the opacity methods listed below is invited to participate. This call will provide an overview of each method, when to use each method and tips on conducting each method.

EPA Method 9

EPA Method 22

Visibility Screens

EPA Method 203A (Modified method 9 for continuous plumes)

EPA Method 203C (Modified Method 9 for intermittent plumes)

Conference Line Instructions

Dial: 1.877.820.7831

Participant Passcode: 468600#

A PowerPoint presentation will be posted at

<http://www.pinalcountyz.gov/airquality/pages/industrialpermits.aspx>